


## 01 Cylinder Bore

■ Rough Boring

Rough Bore Cutter

D Cut Tool



## 01 Cylinder Bore

■ Finish Boring

QT Tool



## 03 Crank Hole

■ Milling for Crank Half Bore


Ball Milling Cutter



## 03 Crank Hole

■ Crank Line Boring

Line Boring Bar



## 01 Cylinder Bore


■ Back Face

Milling Cutter




[Upper Side]

## 01 Cylinder Bore



[Lower Side]

## 03 Crank Hole



## 03 Crank Hole

■ Thrust Wall Facing

Milling Cutter



## 01 Cylinder Bore

■ Honing

ATC Honing Head



## 02 Starter Face

## 02 Starter Face

■ Milling Cutter

Angular Head



## 04 Matching Face

■ Milling Cutter

Multi-Blade Milling Cutter



## 04 Matching Face

■ Deburring

Brush Holder



## 03 Crank Hole

■ Lock Notch Groove

Angular Head

